


Practice Simulation 3 - Key



AUDIOMETRIC SYMBOLS				
	AIR CONDUCTION		BONE CONDUCTION	
	UNMASKED	MASKED	UNMASKED	MASKED
RIGHT EAR	○	△	<	[
LEFT EAR	×	□	>]

Note: Arrows indicate “no response” at the maximum limits of the audiometer.

Audiometer Limits (dBHL) for Pure Tones

Air	Hz	Bone
110	500	65
110	1000	65
110	2000	65
110	3000	65
110	4000	65